













































	9	10	11	12	13
H min	1710mm	1900mm	2090mm	2280mm	2470mm
H max	2115mm	2350mm	2585mm	2820mm	3055mm





 12x	 1x	 13x $\varnothing 108 \times 200 \text{ mm}$	 26x $\varnothing 115 \times 3 \text{ mm}$	 1x	 1x $\varnothing 60 \times 1000 \times 4 \text{ mm}$
 1x $\varnothing 100 \times 3 \text{ mm}$	 1x $\varnothing 28 \times 2 \times 50 \text{ mm}$	 2x	 1x	 29x	 1x
 12x $\varnothing 40 \text{ mm}$	 1x $\varnothing 40 \times 950 \text{ mm}$	 5x $\varnothing 6 \times 1 \times 6000 \text{ mm}$	 3x $\varnothing 40 \text{ mm}$	 11x $\varnothing 15 \times 50 \text{ mm}$	 13x $\varnothing 22 \times 2 \times 1275 \text{ mm}$
 3x $\varnothing 22 \times 2 \times 1030 \text{ mm}$	 1x $\varnothing 22 \times 1 \times 913 + 170 \text{ mm}$	 16x $\varnothing 22 \text{ mm}$	 20x $\varnothing 6 \times 12 \text{ mm}$	 1x	 4x $M20 \times 1000 \text{ mm}$
 13x $M20 \text{ DIN-EN } 24035$	 4x $M20 \text{ DIN } 6334$	 4x $M8 \times 50 \text{ mm}$	 58x $\varnothing 5 \times 30 \text{ mm}$	 40x $\varnothing 4,2 \times 19 \text{ mm}$	 1x $\varnothing 4 \times 50 \text{ mm}$
 8x $\varnothing 6 \times 30 \text{ mm}$	 12x $\varnothing 6 \times 50 \text{ mm}$	 62x $\varnothing 4 \times 25 \text{ mm}$	 1x $M5 \text{ DIN } 9021$	 3x $M8 \times 20 \text{ mm}$	 4x $\varnothing 12 \text{ mm}$
 12x $\varnothing 8 \text{ mm}$	 $\varnothing 6 \text{ mm}$				







3








h	ST1a	ST1b
190 mm	0x	0x
195 mm	1x	0x
200 mm	2x	0x
205 mm	3x	0x
210 mm	4x	0x
215 mm	0x	1x
220 mm	1x	1x
225 mm	2x	1x
230 mm	3x	1x
235 mm	4x	1x









4












30 mm






5







6










3 mm



4 mm





7

